


Bulletin Volume 25-36



Filesize: 5.46 MB

Reviews

Basically no words to clarify. Of course, it is perform, still an amazing and interesting literature. Its been printed in an exceptionally basic way which is only soon after i finished reading through this ebook where actually altered me, change the way i really believe.

(Newton Runolfsson)

BULLETIN VOLUME 25-36

[DOWNLOAD](#)

To read **Bulletin Volume 25-36** PDF, remember to follow the link under and save the document or have accessibility to additional information that are relevant to BULLETIN VOLUME 25-36 ebook.

RareBooksClub. Paperback. Book Condition: New. This item is printed on demand. Paperback. 128 pages. Dimensions: 9.7in. x 7.4in. x 0.3in. This historic book may have numerous typos and missing text. Purchasers can usually download a free scanned copy of the original book (without typos) from the publisher. Not indexed. Not illustrated. 1908 edition. Excerpt: . . . 7 in. to left of left load. At 19 000 lb. a diagonal crack 4 in. high was noted 15 in. to right of right load. At 20 0(H) lb. the cracks were enlarging and at maximum load of 20 100 lb. a diagonal crack 6 in. high was noted 8 in. to right of right load. Load dropped to 11 300 lb. Beam No. 226. 6. At 16 000 lb. diagonal crack 3 in. high marked (1) was noted, at 18000 lb. vertical crack along stirrup 5 in. high marked (2) and at 19 000 lb. the cracks marked (3) and (4). At 20 000 lb. diagonal crack marked (5) appeared and other cracks were enlarging. At maximum, load 21 000 lb. , vertical crack marked (6) was noted: diagonal cracks were lengthening. Load dropped to 14 000 lb. and diagonal crack (1) was opening. Failure by diagonal tension at left end. The stirrups were quite close to sides of beam and were wrapped in paper for the lower 4 inches. Beam No. 227. 5. At 18 000 lb. small vertical cracks were noted 2 in. to right of right load, 4i in. to left of left load, and at first stirrup 2 in. to left of left load on further side of beam. The latter crack was 4 in. long. Failure crack started at bottom of second stirrup 7 in. to right of right load, ran up stirrup 24 in. , then to...

[Read Bulletin Volume 25-36 Online](#)[Download PDF Bulletin Volume 25-36](#)

You May Also Like



[PDF] The Whale Tells His Side of the Story Hey God, Ive Got Some Guy Named Jonah in My Stomach and I Think Im Gonna Throw Up

Click the hyperlink below to get "The Whale Tells His Side of the Story Hey God, Ive Got Some Guy Named Jonah in My Stomach and I Think Im Gonna Throw Up" PDF document.

[Save Document »](#)



[PDF] Animology: Animal Analogies

Click the hyperlink below to get "Animology: Animal Analogies" PDF document.

[Save Document »](#)



[PDF] Index to the Classified Subject Catalogue of the Buffalo Library; The Whole System Being Adopted from the Classification and Subject Index of Mr. Melvil Dewey, with Some Modifications . (Paperback)

Click the hyperlink below to get "Index to the Classified Subject Catalogue of the Buffalo Library; The Whole System Being Adopted from the Classification and Subject Index of Mr. Melvil Dewey, with Some Modifications . (Paperback)" PDF document.

[Save Document »](#)



[PDF] Yearbook Volume 15

Click the hyperlink below to get "Yearbook Volume 15" PDF document.

[Save Document »](#)



[PDF] Froebel s Occupations (Paperback)

Click the hyperlink below to get "Froebel s Occupations (Paperback)" PDF document.

[Save Document »](#)



[PDF] Firelight Stories; Folk Tales Retold for Kindergarten, School and Home (Paperback)

Click the hyperlink below to get "Firelight Stories; Folk Tales Retold for Kindergarten, School and Home (Paperback)" PDF document.

[Save Document »](#)